PD&E STUDY
CORTEZ BRIDGE
From SR 789 (Gulf Drive) to 123rd Street West

FDOT

Financial Project Number: 430204-1-22-01

Alternatives Public Meeting

August 28, 2014

Existing Bridge Condition

Concrete spall and crack on fender pile

Concrete spall and cracks on traffic railing

Internal corroded pile

Corroded bearing

Cracks in deck

Concrete spall on pile cap with exposed corroded steel

Spall on beam with exposed corroded tendon

Corroded steel angle